ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	6	Thanisandra
Street ID	**Street Name**	**Significant Landmark**
W0947	NA	NEAR DASARAHALLI MAIN ROAD
Segment No.	**Total Length (m)**	
6/S-W0947/S061149	128.80	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	128.80	77.605718	13.054759	77.606383	13.055144	W0943	RI-A09

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
IMPROVEMENTS TO ROADS AND DRAINS AT JAMES LAYOUT IN WARD NO. 06 DASARAHALLI VILLAGE LIMITS	2000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	ROADS AND DRAINS
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	IMPROVEMENTS TO ROADS AND DRAINS AT JAMES LAYOUT IN WARD NO. 06 DASARAHALLI VILLAGE LIMITS	006-14-000036
Work Order No.	**Work Order Date**	**Period of Extention**
EE/BTP/KRIDL/W.O/395/2013-14	21/02/2014	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
03/07/2014	02/07/2015	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KARNATAKA RURAL INFRASTRUCTURE DEVELOPMENT LIMITED		0.00
Phone No.	**E-Mail ID**	
800000000		

Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Sidde Gowda	04/02/2016	05/03/2016	Completed
SE	Srinivasa Reddy	04/02/2016	05/03/2016	Completed
EE	Srinivasa Reddy	04/02/2016	05/03/2016	Completed
AEE	Shivakumar	04/02/2016	05/03/2016	Completed
AE	DEVEGOWDA	04/02/2016	05/03/2016	COMPLETED
AE	K DEVEGOWDA	04/02/2016	05/03/2016	COMPLETED

Field Inspection Details

Number of Trees

1

Any Other Information

Name

Devegowda K

Date of Inspection

04/02/2016

Remarks

completed

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.